Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

OTHO THOTOTHO	HAAFIALOITI	Columbus, Ohio 43211	
1. No. BUT-755-9 1011 bills 11110	4. Present Name(s)	i aledno evobaliSP	But:
2. County	Joffe Furniture Co.		155
Butler no syldenossbeller	5. Other Name(s)		N
3. Location of Negatives Hamilton Planning Dept.	Trebel Building , Third Street Depar	rtment Store	1
6. Specific Location	16. Thematic Category.	28. No. of Stories 3	B !
214-216 S. Third Street	commercial	28. No. of Stories 3  29. Basement? Yes No   30. Foundation Material	ES
21, 210 b. Illied beleec	17. Date(s) or Period	No 🗆	er
7 (1)	ca. 1890	30. Foundation Material Stone	, ,
7. City or Town If Rural, Township & 'Hamilton	Vicinity 13. Style or Design Richardsonian Romanesque	31. Wall Construction	1
8. Site Plan with North Arrow	10 Architect or Engineer	Brick load-bearing	
	H 13. Alcintect of Engineer	32. Roof Type & Material	1
a cover	20. Contractor or Builder	gable/slate	
2	21. Original Use, if apparent	33. No. of Bays Front 3 Side 6	
PARKING	commercial	34. Wall Treatment	76
14	22. Present Use	brick/quarryfaced ston	J
waow	commercial	35. Plan Shape	of
	23. Ownership Public 🗆	36. Changes Addition □	fe
9. Coordinates	Private 🗵	(Explain Altered ⊠ in #42) Moved □	Fu
Lat. Long.	24. Owner's Name & Address,	37. Condition	Joffe Furnitur
U.T.M. Reference		Interior	itı
10 710080 4363	150	Exteriorgood	ıre
Zone Easting Northing		38. Preservation Yes □	S
	cture U	Underway? No 🗵	Company
	20. Local Contact Person of Organization	39. Endangered? Yes ☐ By What? No ☒	an
Register? No 🗵 Eligible?		-	~
3. Part of Estab, Yes ☐ 14. District Hist. Dist.? No ☒ Potent'l?	Yes □ No Ø	40. Visible from Yes ⊠ Public Road? No □	
5. Name of Established District		41. Distance from and	ı
	111111	Frontage on Road	
		15'	_
2. Further Description of Important Featur		A	H .
of narrow and wide nectangular	t facade is composed of alternating layer blocks of quarry-faced stone. Two two	rs	rel
story oriel windows below each	n of the twin gables on the front facade		bel
distin&tive elements. Between	n the oriel windows are a set of paired		B
windows at the second and thin	rd story level. The second story cente	r M	ldg
windows have a stone shelf lin	ntel, while the third story windows are		3
43. History and Significance	one which is connected to the top of ori		Trebel Bldg./Third
			ird
	e location of the Third Street Departmen		S
	ers. The building is significant archite Romanesque style as applied to a commerc		tree
Chample of the Richardsonian i	nomanesque style as applied to a commercial	idi ;bulluling in mamilione	et
4. Description of Environment and Outbui	Idings		De
A large parking lot is just no	orth. This structure shares a party wal	l with a c.1870	pa
building which has had quite a	a lot of alteration.	33.515	rtı
		8)	Department
5. Sources of Information		46. Prepared by	E .
P.O.		Rita Walsh	Sto
1927-28 Williams' Hamilton Ci	ty Directory	47. Organization Miami Purchase Ass'n	ore
		ritami rutchase ass it	E .

OHIO PROTECTIVITORY CODED

42. windows contain metal spandrels which are decorated with panels and floral motifs. The gables are topped with stone decorations and contain a narrow slit in the gable peak. The north side of the building has a brick facing, with decorative corbelling in the gable peak. The first story is completely altered, though the addition of corrugated metal canopy and new shop windows.

Continuation Sheet: Specify Section & Item (use additional Continuation Sheets if necessary)

The Ohio Historic Preservation Office files contain additional information for this property. Information may include: newspaper clippings, church bulletins, maps or additional text.